

BELZONA 2200 SERIES ELASTOMERS REPAIR SPLIT CONVEYOR BELT

ID: 5199



PROBLEM

A mechanical breakdown had caused the belt to be split over a length of approximately 100 feet.

APPLICATION SITUATION

Split belt repair

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1

BELZONA FACTS

The use of the two Belzona products allowed the plant to repair the damage in situ, saving many hours of downtime.

INDUSTRY

Mining & Quarrying

LOCATION

BC, Canada

APPLICATION DATE

June 2000

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2911 (QD Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Conveyor system in need of repair
2. The damaged portions of the belt were held together using mechanical fasteners
3. Close-up of fasteners and the prepared belt surfaces conditioned with Belzona 2911
4. The completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

