

BELZONA REBUILDS DIVERTER VALVES FOR CEMENT PLANT

ID: 5204



PROBLEM

The seating area of the diverter valve would wear.

APPLICATION SITUATION

Worn diverter valve

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-1

BELZONA FACTS

The use of Belzona 1811 allows the maintenance department to rebuild the diverter valves on a regular basis on site and often in place saving both downtime and replacement costs

INDUSTRY

Cement

LOCATION

BC, Canada

APPLICATION DATE

1990

PRODUCTS

Belzona 1811 (Ceramic Carbide)

SUBSTRATE

Hardened Steel

PHOTOS

Two valves in workshop waiting to be rebuilt Worn areas where valve flap sits against the valve body are marked out with chalk and rebuilt Rebuilt valve. Area ahead and behind valve flap were rebuilt

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

