

BELZONA REPAIRS A VACUUM PUMP

ID: 5375



PROBLEM

The outlet port had corroded to the point a hole had formed; a competitor's patch product had been applied but failed after a short time.

APPLICATION SITUATION

This vacuum pump handles mildly acidic filtrate.

APPLICATION METHOD

The application was carried out in accordance with the Belzona Know-How System Leaflet CEP-6.

BELZONA FACTS

This facility has a long history of successful Belzona repairs.

INDUSTRY

Fluid Flow

LOCATION

British Columbia, CA

APPLICATION DATE

August 2014

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Steel

PHOTOS

1. Image of the leak
2. The surface preparation requires a number of tools due to the tight space
3. Exposed hole is a bit larger than expected
4. The application complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

