


BELZONA REPAIRS A CONVEYOR BELT

ID: 5432



PROBLEM

Conveyor belt had a 2" x 2" piece of rubber missing.

APPLICATION SITUATION

Conveyor belt with a piece missing.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The hole in the belt was filled with Belzona 2311.

BELZONA FACTS

Customer had made larger repairs with excellent results so it was only natural to repair this hole also. Belzona 2311 enabled the repair to be carried out with minimal downtime.

INDUSTRY

General Industry

LOCATION

South Louisiana, USA

APPLICATION DATE

September 2013

PRODUCTS

Belzona 2311 (SR Elastomer)
Belzona 2911 (Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. The area prepared for repair
2. Application is complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

