

BELZONA SAVES A CRUSHED CRUSHER

ID: 5638



PROBLEM

The concrete crusher pedestal developed cracks and caused excessive vibration during crusher operations, leading to premature bearing failure and production to slow down.

APPLICATION SITUATION

Hard Rock Mine concrete crusher base.

APPLICATION METHOD

Cracks were vee'd out by hand, drilled with injection holes, prepped and faired out with Belzona 4911 and Belzona 4111. Upon initial cure of Belzona 4111, Belzona 4151 resins were injected through the prepared ports under high pressure to chase and fill the underlying voids and cracks. Belzona 1221 was used to seal the injection holes.

BELZONA FACTS

Customer had previously tried mortar repairs, but the cracks ran very deep into the concrete and vibration caused the mortar to fail. Resin injection was suggested and customer felt it was a cost effective solution.

INDUSTRY

Mining & Quarrying

LOCATION

Mining Plant, USA

APPLICATION DATE

Fall, 2014

PRODUCTS

Belzona 1221 (Super E-Metal)
Belzona 4911 (Magma TX Conditioner)
Belzona 4111 (Magma-Quartz)
Belzona 4151 (Magma-Quartz Resin)

SUBSTRATE

Concrete

PHOTOS

1. Crusher overview
2. Series of cracks in foundation
3. Prepped, conditioned and injection screws ready to be overcoated with Belzona 4111
4. Injecting Belzona 4151

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

