


MAKE HAY WHILE THE SUN SHINES

ID: 576



PROBLEM

Tire was damaged but cords still in good condition. No replacement available.

APPLICATION SITUATION

Damaged obsolete U.S. Royal 5.50-16 implement tread tire from J.I. Case 140w hay baler.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona® Know-How System Leaflet MPT-10.

BELZONA FACTS

A wider tire would not fit the space between the baler and the tire. No manufacturer makes this size tire. A taller tire would cause an uneven hay pickup situation.

INDUSTRY

General Industry

LOCATION

Farmer - Kansas U.S.A.

APPLICATION DATE

July 2005

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged tire.
2. All loose rubber removed from tire.
3. Release agent was applied to a mold. Belzona 2211 was applied to the tire and mold.
4. The tire repaired.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

