



CONVENIENT BELZONA CONVEYOR BELT REPAIR

ID: 583



PROBLEM

Joint failing due to moisture.

APPLICATION SITUATION

Previously vulcanized joints in coal conveyor utilizing Tip Top.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-6.

BELZONA FACTS

The Belzona repair minimizes down-time and is accomplished without specialist vulcanizing equipment. this application lasted in excess of three years and Belzona is routinely used at the facility for belt repairs.

INDUSTRY

Power

LOCATION

Power Industry, Bulgaria

APPLICATION DATE

October 2003

PRODUCTS

Belzona 2311 (SR Elastomer)
Belzona 2911 (QD Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Original joint
2. Repair area masked off and conditioned
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

