

RESEATING PIN BUSH WITH BELZONA ON CATERPILLAR 980 LOADER

ID: 6432



PROBLEM

Lack of lubrication had caused abrasion in the bush housing, which led to a diameter increase of 30 mm from the original dimension. This meant a loose fitting bucket pin and unstable use of the equipment.

APPLICATION SITUATION

At a separation mine, one of the large Caterpillar 980 Wheel Loaders was suffering pin housing damage due to lack of lubrication.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System leaflet MPT-8. The surface was prepared by grinding and a new bush was bonded into place using Belzona 1111. Other bushing was in a good condition. In order to ensure the bushes were in correct alignment a dummy shaft was used to locate the bushing.

BELZONA FACTS

The application was completed in four hours and through the use of cold-curing materials, involved no heat. This method shortened the downtime of the machine and the repair was performed in situ without dismantling or machining of the frame.

INDUSTRY

Mining & Quarrying

LOCATION

Mine, Skopje, Macedonia

APPLICATION DATE

February 2017

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Damaged pin bush housing 2. New bushing installed with Belzona 1111 3. A dummy shaft was used to locate the bushing 4. View of Caterpillar 980 machine

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

