

EASY LINTEL REPAIR WITH BELZONA

ID: 6435



PROBLEM

The entire front face of the concrete “Boot” lintel had failed due to re-bar corrosion. The customer wanted a long-term solution without having the need to disturb the structure.

APPLICATION SITUATION

Residential Property

APPLICATION METHOD

Application carried out in accordance with Belzona system leaflet WPA-4

BELZONA FACTS

The application was completed in just 2 hours. Conventional replacement would have been costly, time consuming and disruptive. The customer has used Belzona 4141 before and is very happy with the results.

INDUSTRY

Buildings & Structures

LOCATION

Housing Association, Cleveland, UK

APPLICATION DATE

2017

PRODUCTS

Belzona 4141 Belzona 4911

SUBSTRATE

Concrete and Steel

PHOTOS

1. Overview (after repair)
- 2 & 3. Damaged Lintel
4. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

