


BELZONA REPAIRS HOLED VALVE HOUSING

ID: 699



PROBLEM

Cavitation had caused the valve housing to become holed

APPLICATION SITUATION

Valve Housing

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-8.

BELZONA FACTS

The plant did not have a reserve valve in there warehouse and a new replacement would take weeks to be delivered. Belzona solved the problem in just two days.

INDUSTRY

Buildings & Structures

LOCATION

Petrochemical Plant, Macedonia

APPLICATION DATE

May 2001

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1341 (Supermetalgilde)

SUBSTRATE

Grey Cast Iron

PHOTOS

1. Holed valve housing.
2. Metal plates used to reinforce the exterior.
3. Rebuilt housing.
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.