


BELZONA PROTECTS FRANCIS TURBINE RUNNER

ID: 7591



PROBLEM

Erosion/Corrosion

APPLICATION SITUATION

Francis Turbine Runner was suffered extensive damage.

APPLICATION METHOD

The application was carried out in accordance with the Belzona Know-How System Leaflets CEP-1, CEP-3 and CEP-5.

BELZONA FACTS

This was not first Belzona protection of Francis turbine runner for this customer. The client was so pleased with performance of the previous repair they ordered this repair and for a another turbine.

INDUSTRY

Power

LOCATION

Electricity Producer, Slovakia

APPLICATION DATE

2014

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Steel

PHOTOS

1. Turbine in very bad condition
2. Repair in progress
3. Repair in progress
4. Turbine like new

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

