

BELZONA CHOCKING REPAIR ON GEAR MOUNTING

ID: 8061



PROBLEM

Gear mounting not working at full efficiency due to misalignment.
Repair work need to concrete area prior to chocking.

APPLICATION SITUATION

Re-levelling a steel foundation slab of a mill gear and the foundation of the mill on the plate.

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet GSS-2. Placing of the steel foundation slab using the Belzona 4111. Chocking the foundation of the mill plate using Belzona 7111.

BELZONA FACTS

Belzona won the chocking project over a competitor due to the competence and back up support of the local distributor.

INDUSTRY

General Industry

LOCATION

Szarbków, Poland

APPLICATION DATE

2019

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 7111

SUBSTRATE

Concrete

PHOTOS

1. Gear Equipment Picture
2. Application of Belzona 4111
3. Application of Belzona 7111
4. Chocking application complete.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

