

BELZONA SAVES FISHING BOAT TAILSHAFT

ID: 818



PROBLEM

Severely worn bushing on the propeller shaft damaged the cutlass bearing causing vibration on the fishing vessel.

APPLICATION SITUATION

Worn Propeller Shaft Bushing

APPLICATION METHOD

Repair was carried out in accordance with Belzona Know-How System Leaflet MPT-1

BELZONA FACTS

Replacement with new bronze sleeves would be very costly and too time consuming.

INDUSTRY

Marine

LOCATION

Fishing Company, Philippines

APPLICATION DATE

June 2006

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Bronze

PHOTOS

1. Worn bronze bushing
2. Surface preparation using machining technique
3. Application of Belzona 1111
4. Application of Belzona 1111 being completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

