

RESTORING AND COATING E5B HEAT EXCHANGER FACE

ID: 9288



PROBLEM

Galvanic corrosion on the tube face, caused by contact of 2 dissimilar metals.

APPLICATION SITUATION

Rebuilding and coating a heat exchanger in situ, the heat exchanger is used to transfer heat used in the steel manufacturing process.

APPLICATION METHOD

The application was carried out in accordance with system leaflet HEX-01.

The application area was marked out before the tube face was grit blasted to SA2.5, achieving a minimum 75-micron profile. After blasting, the tube face was rebuilt with Belzona 1111, followed by 2 coats of Belzona 1321, each coat was applied at 250-375 microns. After the Belzona had cured, a visual inspection was carried out and any areas requiring touch-ups were marked up, abraded, and then re-coated. Before the HEX was put back in service, the equipment passed a hydrostatic test carried out by the client under a pressure of 30 kg/cm².

BELZONA FACTS

The client was satisfied with the solution as the application was carried out in situ and avoided the need to disassemble the HEX.

INDUSTRY

Steel & Metal Processing

LOCATION

Brazil

APPLICATION DATE

July 2011

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon steel

PHOTOS

- 1.) Before application
- 2.) After Blasting
- 3.) Applying Belzona 1111 for the rebuild
- 4.) Final application - removal of corks

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA