



PVC CHILLER INTERNAL REBUILD W/ BELZONA 1121 AND BELZONA 1321

ID: 9432



PROBLEM

Client found extreme corrosion and had minimal down time for repair.

APPLICATION SITUATION

Downtime was minimal and repair was completed before weekend ended.

APPLICATION METHOD

Abrasive blasted entire areas to be coated to SSPC SP 10 as per product manufactures recommendations.

Rebuilt damaged internal areas as identified with Belzona 1121

Coated all internal wet areas identified with Belzona 1321 Ceramic S Metal

BELZONA FACTS

Minimal downtime which allowed the equipment to be put back into service quickly.

INDUSTRY

Oil & Gas

LOCATION

Plaquemine, LA

APPLICATION DATE

June 2024

PRODUCTS

Belzona 1121 (Super XL-Metal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Before Repair
2. After Repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

