

FRITO LAY SHAFT REPAIR

ID: 9712



PROBLEM

Customer has a shaft that was worn due to bearing failure.

APPLICATION SITUATION

Customer needed a repair done as soon as possible.

APPLICATION METHOD

Shaft was prepared and cleaned Belzona 1111 was applied

BELZONA FACTS

Customer chose Belzona to return back to service in a timely manner.

INDUSTRY

General Industry

LOCATION

Fayetteville TN

APPLICATION DATE

October 2017

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Shaft was worn out.
2. Application of Belzona 1111
3. Sanding out for final touch of the repair.
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

