

KNOCK OUT DRUM

ID: 9876



PROBLEM

The knock out drum had pitting on 55% of the tank. Sherwin Williams Company did not have a pitting filler.

APPLICATION SITUATION

Belzona 1511 had to be ship on a hotshot after Sherwin Williams Company drop the ball and did not supply the product.

APPLICATION METHOD

The Application was don by hand

BELZONA FACTS

Sherwin Williams Company did not have the product in die country and it was a 4 week del.
Oklahoma and Miami had the stock and did the job.

INDUSTRY

Oil & Gas

LOCATION

Oklahoma

APPLICATION DATE

May 2025

PRODUCTS

Belzona 1511 (Super HT-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Looking in to the Knock out drum for the outside .
2. Contractor applying Belzona 1511
3. Looking into the Knock out drum for the outside Contractor applying Belzona 1511
4. Looking into the Knock out drum for the outside Contractor applying Belzona 1511

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

