BELZONA REBUILDS KORT NOZZLE

ID: 3128





PROBLEM
OnlY 16 hours was available to carry out repairs to the erosion damage.

APPLICATION SITUATION
Badly corroded kort nozzle

APPLICATION METHOD
Application was carried out in accordance with Belzona Know-How System Leaflets SOS-1. After grit blasting, Belzona® 1311 was used to rebuild eroded metal and provide future erosion corrosion protection.

BELZONA FACTS
Client had no option but to use Belzona in the short tiome scale available. Large portfolio of similar jobs helped client to make this decision.

INDUSTRY
Marine

LOCATION
Shipping Company, Santos, Brazil

APPLICATION DATE
December 2011

PRODUCTS
Belzona 1311 (Ceramic R Metal)

SUBSTRATE
Cast iron

PHOTOS

1. Eroded area
2. Belzona 1311 aplication
3. Completed Belzona 1311 aplication
4. Vessel ready to refloat.

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.