

BELZONA KEEPS BEET SLICER RUNNING

ID: 10



PROBLEM

Bearing failure damaged beet slicer shaft

APPLICATION SITUATION

Beet slicer shaft

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet MPT-2.

BELZONA FACTS

Repair allowed customer to save time and money by avoiding disassembly of machinery.

INDUSTRY

Sugar

LOCATION

Sugar Beet Mill in North Dakota, U.S.A.

APPLICATION DATE

1983

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. View of damaged shaft .
2. Application of Belzona 1111 (Super Metal).
3. Use of a former to rebuild shaft.
4. Completely rebuilt shaft.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.