

BELZONA GIVES OLD PUMP NEW LEASE OF LIFE

ID: 1006



PROBLEM

Deterioration due to bimetallic corrosion and sea water erosion.

APPLICATION SITUATION

Sea Water Pump

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System leaflets CEP-3 & -5.

BELZONA FACTS

Due to the pump's condition, a new pump was considered but Belzona application proved to be a long term cost effective alternative.

INDUSTRY

Power

LOCATION

Coal-fired power plant, Croatia

APPLICATION DATE

April 2007

PRODUCTS

Belzona 1311 (Ceramic R Metal) Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Cast iron

PHOTOS

1. Damaged seawater pump
2. Applying Belzona 1311
3. Belzona 1311 application complete
4. Belzona 1321 applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

