

BELZONA IN THE PRESS

ID: 1007



PROBLEM

A screw fell into the printing machine causing damage to the roller.

APPLICATION SITUATION

Printing machine roller.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona System Leaflet MPT-2.

BELZONA FACTS

Belzona quickly and effectively got the printing machine back to work, saving time and money and most importantly avoiding excessive downtime enabling the printing house to meet its deadlines.

INDUSTRY

General Industry

LOCATION

Printing house, Croatia

APPLICATION DATE

March 2006

PRODUCTS

Belzona 1221 (Super E Metal)

SUBSTRATE

Steel

PHOTOS

Printing machine Damaged roller with imprint from screw clearly evident
Ongoing application Application completed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

