

DAMAGE FROM TRAILER LANDING LEGS, REPAIRED BY BELZONA

ID: 10073



PROBLEM

The Landing legs on the 40' trailers had worn depressions into the concrete floors. These were causing problems with fork lift traffic and other vehicles as some of the depressions were over 40mm deep

APPLICATION SITUATION

The area had to be out of action for as short a time as possible. Belzona 4131 gave an opportunity for the areas to be replaced easily over 1 weekend

APPLICATION METHOD

Cleans and dried the concrete using absorbent kit

All loose and friable material removed

Belzona 4911 applied with short bristled brush

Belzona 4131 applied by gloved hand and compressed using finishing trowel

BELZONA FACTS

The works were finished in one afternoon and cured before the business re-opened on the Monday morning. The works were carried out under Belzona supervision using their own staff in order to enable them to pursue further repairs as and when they needed to do them

INDUSTRY

Chemical & Petrochemical

LOCATION

Alfreton

APPLICATION DATE

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Showing landing legs causing wear to concrete parking area near loading doors
2. Areas cleaned and dried, the conditioned with Belzona 4911
3. In-house training given to their own team to help them carry out simple repairs in-house
4. Completed with Belzona 4131 and feather edged

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

