

# CONCRETE REPAIRS TO HEAVY MANUFACTURING FLOOR

ID: 10074



## PROBLEM

Areas of a heavy industrial floor were compromised and had started to break up, some of which had been repaired previously, though these repairs had failed

## APPLICATION SITUATION

Repairs had been attempted before and had continually failed. The Local ASR attended site to offer full training in the application of the Belzona 4000 series.

## APPLICATION METHOD

Clean all area  
Mix and apply Belzona 4911 TX conditioner  
Mix and apply Belzona 4131

## BELZONA FACTS

The local Belzona ASR supported to application and trained the in-house colleagues on the proper procedure to effect a concrete repair. The site was visited earlier this year (2025) and found to be in excellent order

## INDUSTRY

Heating, Ventilation & Air Conditioning

## LOCATION

Doncaster

## APPLICATION DATE

March 2022

## PRODUCTS

Belzona 4131 (Magma-Screed)  
Belzona 4911 (Magma TX Conditioner)

## SUBSTRATE

Concrete

## PHOTOS

1. Showing one of the heavily damaged areas
2. Cleaning area prior to application
3. Application of Belzona 4911 TX Conditioner
4. Completed application using Belzona 4131

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

