

BELZONA COOLING TOWER BASIN REPAIR

ID: 10091



PROBLEM

Cooling tower basin was experiencing deterioration and required a face lift.

APPLICATION SITUATION

Cooling tower basin was experiencing deterioration and required a face lift.

APPLICATION METHOD

Power tool cleaning was carried out on the surface before the pitting was covered with Belzona 1161. Two coats of Belzona 5831 was then applied afterwards.

BELZONA FACTS

Belzona was able to achieve a fast curing application with no limitations regarding the moisture and humidity level of the substrate.

INDUSTRY

Buildings & Structures

LOCATION

Hamilton, ON.

APPLICATION DATE

November 2025

PRODUCTS

Belzona 1161 (Super UW-Metal)
Belzona 5831LT

SUBSTRATE

Carbon steel

PHOTOS

1. Basin before repair
2. Basin after repair
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

