

BELZONA REPAIR AND PROTECTION OF STABILISER SHAFT

ID: 101



PROBLEM

Severe pitting corrosion in-board of bearing.

APPLICATION SITUATION

Stabilizer shaft

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet SOS-1.

BELZONA FACTS

Belzona was used because our repair could be done without dismantling.

INDUSTRY

General Industry

LOCATION

Shipping Company, Monaco

APPLICATION DATE

1995

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the stabiliser shaft
2. After grit blasting, degree of erosion-corrosion damage clearly evident
3. Application of Belzona 1111 being completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

