

BELZONA RESURFACES LAB TABLES

ID: 1010



PROBLEM

At Georgia Tech, customer wanted to provide a durable surface without having to replace soapstone tables of 40 years of wear and tear have degraded tables.

APPLICATION SITUATION

Surface of the lab table.

APPLICATION METHOD

Sanding tables to provide a good profile. Then applied two coats of Belzona 5811.

BELZONA FACTS

The university was able to refurbish the tables and labs at a fraction of the cost to replace. The table tops were refurbished in two days as compared to two weeks for replacement.

INDUSTRY

Buildings & Structures

LOCATION

Atlanta, GA, USA

APPLICATION DATE

February 2008

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Soapstone

PHOTOS

1. View of original table
2. Application of first coat
3. Completed application
4. After 5 years, another lab top table was being repaired. Lab was being rebuilt, but the tops were remained.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

