

BELZONA 1813 SAVES FIBERGLASS SPRAY HEADERS

ID: 10104

2



3



4



PROBLEM

Fiberglass spray headers in pre-scrubber tank were worn thru from the spray header itself getting plugged and spraying in different locations and wearing top of header piping.

APPLICATION SITUATION

The application was done on new piping now in contractors shop. The top half of all new piping was prepped manually and 1/8 to 1/4 inch Belzona 1813 was applied. Initially the repairs were done inside tank and new piping was ordered. The Belzona 1813 worked so great that they wanted the new piping coated as well.

APPLICATION METHOD

New fiberglass piping was manually prepped with grinders, cleaned and Belzona 1813 was applied by hand.

BELZONA FACTS

The Belzona 1813 was lasting better than the fiberglass repair and was cheaper to install than the traditional repair kits.

INDUSTRY

Oil & Gas

LOCATION

Beulah,North Dakota

APPLICATION DATE

May 2020

PRODUCTS

Belzona 1813

SUBSTRATE

Composite

PHOTOS

1. Application of Belzona 1813 to new headers in their shop.
2. Smoothing out the Belzona 1813 on headers.
3. Closeup of contractor finishing up on a header.
4. Finalized application and contractors wearing new Belzona t-shirts!

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

