

SAVED SPOOL PIECE WITH BELZONA

ID: 10146



PROBLEM

The customer discovered this spool piece during an outage and needed a quick turnaround to coat the surface.

APPLICATION SITUATION

The customer discovered this spool piece during their spring outage and needed a quick turnaround to get this back in place to get back up and going.

APPLICATION METHOD

For this application we first blasted the surface to a 3 mil profile followed by cleaning with 100% MEK. Next we applied two coats of Belzona 1321 using a stiff bristle brush.

BELZONA FACTS

They chose Belzona due to other applications we have completed for them and the durability of the Belzona 1321 along with being able to have this piece completed and back to the customer in less than 24 hours saving them thousands in down time.

INDUSTRY

Power

LOCATION

Decatur, AL

APPLICATION DATE

March 2025

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Before picture of the spool piece.
2. You can see the old coating had started to wear off.
3. After blasting to a 3 mil profile and first coat of Belzona 1321
4. Completed photo of spool piece with two coats of Belzona 1321

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

