

BELZONA REPAIRS RUBBER LINED BRINE TANK

ID: 1020



PROBLEM

Rubber lining had been damaged locally. It was too costly to get specialist tank repair company to come and make repair.

APPLICATION SITUATION

Rubber lined brine tank in over house of paper mill

APPLICATION METHOD

Application was carried out in accordance with the Belzona Know-How System Leaflet TCC-3.

BELZONA FACTS

Would have cost over \$2500 for specialist tank company to come make the repair. Used one unit of Conditioner and one unit of Belzona® 2111. Repair was made one day and tank was put back in service the next day.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill, Alabama

APPLICATION DATE

February 2008

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Steel and Rubber

PHOTOS

1. Opening to the tank
2. Exposed metal where repair to be made
3. Conditioner applied after grinding
4. Repair completed with Belzona 2111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

