

BELZONA IN-SITU REBUILD OF DECK WINCH

ID: 103



PROBLEM

Wear on shaft was in the way of the cable drum

APPLICATION SITUATION

Shaft of deck winch

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet MPT-1. Portable lathe was used to machine shaft in place without removing or complete dismantling.

BELZONA FACTS

Belzona application safe and easy enough to carry out in-situ.

INDUSTRY

Oil & Gas

LOCATION

Liquefied Natural Gas Carrier, France

APPLICATION DATE

1997

PRODUCTS

Belzona 1131

SUBSTRATE

Steel

PHOTOS

1. Belzona 1131 being applied to the prepared shaft
2. In-situ machining of the Belzona 1131 being carried out
3. The completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

