

BELZONA KEEPS CUSTOMERS ROLLING

ID: 1033



PROBLEM

After the rental was returned they saw the damage and needed a repair right away, knowing the unit was booked to go right back out.

APPLICATION SITUATION

Tire repair

APPLICATION METHOD

Application was carried out using a modified Belzona Know-How System Leaflet SHM-1. The Surface was roughed with roughing brush, Conditioned then gouges in tire repaired with the Belzona® 2311.

BELZONA FACTS

Belzona Elastomer was chosen for this job because of its durability, ease of application and how quickly they could get the unit back into the field again.

INDUSTRY

General Industry

LOCATION

Plant rental company, Augusta SC

APPLICATION DATE

December 2007

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damage to the tire
2. After the roughing surface conditioned
3. Belzona 2311 completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

