


BELZONA HELPS TO STOP LEAKAGE

ID: 1036



PROBLEM

Leakage from the pipe caused by erosion/corrosion.

APPLICATION SITUATION

Natural gas transporting pipe in power plant.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

BELZONA FACTS

The leakage from the pipe had to be stopped by the fastest possible way. In the situation conventional repair by welding was not possible. The hole was sealed with Belzona in only a couple of hours.

INDUSTRY

Power

LOCATION

Power plant, Bulgaria

APPLICATION DATE

June 2003

PRODUCTS

Belzona 1221(Super E Metal)
Belzona 1291 (ES-Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the pipe to be repaired at high level more than 10 m above the ground
2. The hole revealed and surrounding area roughened
3. Reinforcement patch applied with Belzona 1221 pressed over the leak

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

