

BELZONA REPAIR OF CONVEYOR BELT

ID: 1037



PROBLEM

Mechanical damage on the protector/scrapper was exposing the metal reinforcement

APPLICATION SITUATION

5 km conveyor belt for transporting coal to the power plant

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

The customer required the repair with minimum down-time. Belzona was chosen for its effective simple and fast accomplishment without special equipment as per alternative hot vulcanization method.

INDUSTRY

Power

LOCATION

Power plant, Bulgaria

APPLICATION DATE

August, 2002

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. View of the conveyor belt facility
2. Conditioning with Belzona 2911
3. Belzona 2311 used to rebuild the damage

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

