

BELZONA 4811 REPAIRS TO CONTIMIX HYDROPULPER IN PAPER MILL

ID: 104



PROBLEM

Basalt tile lining damaged and efficiency of machine impaired.

APPLICATION SITUATION

Contimix Hydropulper used to shred waste paper.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How system SHM-7.

BELZONA FACTS

Basalt tiles are individually made to size and shape and were not readily available. Repairs with Belzona ensured production was not unduly interrupted. Belzona® 4811 ensured in-fill areas were capable of withstanding the high abrasion similar to the basalt.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill in the UK

APPLICATION DATE

1998

PRODUCTS

Belzona 4811

SUBSTRATE

Stainless steel and Basalt

PHOTOS

1. View of equipment with lid raised showing the pulping blade
2. The area of damaged tiles
3. Tiles re-bonded and grouted with Belzona 4811

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

