

# BELZONA LEAK SEALING EMERGENCY

ID: 1046



## PROBLEM

Line sprung a leak in an odd spot right next to a chemical injection nozzle which made the repair impossible with a normal clamp.

## APPLICATION SITUATION

Main effluent line operating at 35psi could not be shut down since plant already operating above normal capacity.

## APPLICATION METHOD

Application was carried out in accordance with the Belzona Know-How System Leaflet VPF-11a.

## BELZONA FACTS

Belzona saved the day for this plant as they feared this leak would keep growing. Two years later this repair is still holding fine.

## INDUSTRY

Water / Wastewater

## LOCATION

Waste Water Utility / Oklahoma

## APPLICATION DATE

April, 2006

## PRODUCTS

Belzona 1291 (ES Metal) Belzona 1221 (Super E Metal)

## SUBSTRATE

Carbon steel

## PHOTOS

1. Rags over leak to keep the spray down
2. Sanding the leak and getting wet
3. Belzona 1291 applied and leak stopped
4. Belzona 1221 applied and leak fixed for good

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

