


OVERNIGHT FLOOR REPAIRS COMPLETED WITH BELZONA

ID: 1051



PROBLEM

Floor was eroded and very slippery causing a safety hazard and slowing workers down. There is only an 8 hour window for this repair.

APPLICATION SITUATION

Floor around the case wash machine.

APPLICATION METHOD

Application was carried out using a modified Belzona Know-How System FPA-1.

After cleaning and grinding floor, pre-warmed Belzona® 4111 mixed as a slurry was applied with a squeegee and surface loaded to rejection with Belzona non-slip aggregate.

BELZONA FACTS

Belzona cures fast when other products have failed to cure in the time allotted. This repair still looks like new after more than six months.

INDUSTRY

Buildings & Structures

LOCATION

Dairy, Oklahoma U.S.A.

APPLICATION DATE

October, 2007

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Dirty floor
2. Surface preparation
3. Applying tape & Belzona 4911 Conditioner
4. Squeegee coat of Belzona 4111 slurry & non-slip applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

