

BELZONA PREVENTS SLIPPING IN WASH AREA

ID: 1053



PROBLEM

Previous applications of non-slip surfacing had peeled so necessitating a more permanent solution.

APPLICATION SITUATION

Walkway in wash station for casings is always wet.

APPLICATION METHOD

Application was carried out using a modified version of Belzona Know-How System FPA-3. after thorough cleaning and abrading, two coats of Belzona® 4151 with a colored aggregate were then applied.

BELZONA FACTS

This floor is two years old and still in perfect condition.

INDUSTRY

General Industry

LOCATION

Dairy, Oklahoma USA

APPLICATION DATE

June, 2006

PRODUCTS

Belzona 4151 (Magma Resins)

SUBSTRATE

Concrete

PHOTOS

1. Surface being cleaned
2. First coat
3. Second coat
4. Almost two years later the floor although dirty is 100% intact

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

