

BELZONA KEEPS VEHICLES MOVING

ID: 1055



PROBLEM

During the rain or snow, vehicles were slipping when moving off the brake testing rollers.

APPLICATION SITUATION

Application of grip system to provide better traction on the workshop floor

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona 5811 was applied by brush in a diagonal stripe pattern and blinded with Belzona® 9211.

BELZONA FACTS

Customer was looking for quick and “clean” solution. The Belzona solution provided an effective grip system as well as chemical resistance to any spillage or leaks that may occur. The system has proven itself in service.

INDUSTRY

General Industry

LOCATION

Vehicle Testing Station Bratislava, Slovakia

APPLICATION DATE

2006

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 9211 (Suregrip aggregate)

SUBSTRATE

Floor tiles

PHOTOS

1. Vehicle Testing Station
2. Vehicle during the brake testing
3. 2 years in service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

