

BELZONA PROTECTS CHEMICAL CONTAINMENT AREAS

ID: 1071



PROBLEM

Occasional spills during the operations of filling up the tanks caused major damage to the previous coating

APPLICATION SITUATION

Four chemical containments for polyester tanks filled with sodium hypochlorite

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Belzona® 4311 had already proven itself within the power industry that it is a very effective coating for many chemicals

INDUSTRY

Power

LOCATION

Coal Power Plant, Galicia, Spain

APPLICATION DATE

February 2008

PRODUCTS

Belzona 4311 (Magma CR1) Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Removing the old coating
2. Blasting the surface to be coated
3. Applying the second layer of Belzona 4311 over the first coat
4. One of the containment areas after one month

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

