

BELZONA FLEXIBLE MEMBRANE SEALS LEAKING CONCRETE DECK

ID: 1077



PROBLEM

Water, leaking through the concrete deck, was falling on the cars parked beneath and damaging the paintwork

APPLICATION SITUATION

Leaking concrete deck over parking garage

APPLICATION METHOD

Application completed in accordance with a modified version of Belzona Know-How System Leaflet RPA-10.

BELZONA FACTS

Various crack sealing products had been tried with little little to no success.

A recent check in 2008 reveals the deck coating to still be in service.

INDUSTRY

Buildings & Structures

LOCATION

Property Management Company

APPLICATION DATE

August 1995

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Exposed aggregate concrete

PHOTOS

1. The deck prepared by pressure washing
2. After application of Belzona 3911 to concrete surfaces and Belzona 3921 Aluminum surfaces (window and door frames), Belzona 3111 was applied
3. View of deck taken in 2005 after 10 years of service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

