

BELZONA ELASTOMER SEALS CONCRETE PARKING DECK

ID: 1080



PROBLEM

A previous application by another contractor had failed in a very short space of time leading to water entering the shop below.

APPLICATION SITUATION

Various cracks and faulty seams on concrete parking deck.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

Heavy rains after the application had been completed revealed that the area was now completely water-tight.

INDUSTRY

Buildings & Structures

LOCATION

Shopping Mall - Vancouver, BC

APPLICATION DATE

November 2007

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. All joints were ground clean to remove all traces of the failed material
2. All joints were conditioned with Belzona 2911 prior to injecting the Elastomer
3. Completed application with all the joints and cracks sealed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

