


BELZONA PROTECTS AERATOR IN WATER TREATMENT PLANT

ID: 1081



PROBLEM

The welded component required protection from bi-metallic corrosion

APPLICATION SITUATION

Aerator in water treatment process.

APPLICATION METHOD

Application completed in accordance with Belzona Know-How System Leaflet SHM-11.

BELZONA FACTS

A similar piece of equipment built 6 years previously and protected with Belzona® 1321 had provided extremely good service.

INDUSTRY

Water / Wastewater

LOCATION

Waste Water Treatment Plant, British Columbia

APPLICATION DATE

November 2007

PRODUCTS

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Stainless Steel

PHOTOS

1. Completed aerator unit in the fabricating shop after grit blasting
2. Close up view of the equipment
3. Completed application, 2 coats of Belzona 1321
4. Protected aerator in service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

