

BELZONA GETS TRACTOR BACK ON TRACKS

ID: 1094



PROBLEM

Abrasion of rubber on inside surface of tracks

APPLICATION SITUATION

Rubber tractor tracks

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-how System Leaflet SHM-1.

BELZONA FACTS

Belzona is the approved repair method by Manufacturer. Whole repair will cost £250. New tracks cost £5500.

INDUSTRY

General Industry

LOCATION

Agricultural Equipment Suppliers, UK

APPLICATION DATE

March 2008

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Rubber / steel

PHOTOS

1. General view of track before repair
2. Close up of damaged area
3. After repair
4. Back on track

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

