



BELZONA PROTECTS PAPER MILL ROLLER GEARBOX COVER

ID: 1095



PROBLEM

Corrosion protection

APPLICATION SITUATION

External lining for Supports and Covers of paper rollers

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The equipment needed to have long term corrosion protection due to the very high cost of replacements and quality issues caused by corrosion/contamination of paper by corrosion or flaking paint.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill, Italy

APPLICATION DATE

March 2007

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Mild Steel

PHOTOS

1. First coat of Belzona 5811
2. Second coat of Belzona 5811
3. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

