

BELZONA REPAIRS AND PROTECTS ROOF

ID: 1099



PROBLEM

Localised leakage and overall corrosion problem

APPLICATION SITUATION

The building is a public sport facility with a roof surface area of 1400m².

APPLICATION METHOD

Localised repairs carried out in accordance with Belzona Know-How System Leaflet RPA-1. Further corrosion protection achieved by spray application of Belzona® 3111 system.

BELZONA FACTS

Belzona solution stopped the water ingress into the sports facility and also gives corrosion protection to the overall steel surface.

INDUSTRY

Buildings & Structures

LOCATION

Public Gymnasium, France

APPLICATION DATE

July 2002

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Steel roof with Aluminium coating

PHOTOS

1. Localised water ingress
2. Repair to the seams
3. Application extended to cover Corroded roof
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

