

BELZONA PROVIDES SAFE WELCOME

ID: 1100



PROBLEM

During rain or snow people have slip problems on the ramp into the offices.

APPLICATION SITUATION

Main entrance into companies offices.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 1321 was applied by brush in conjunction with Belzona® 9211 (Supergrip Aggregate). Templates were used to create logo.

BELZONA FACTS

Customer achieved a quick, distinctive and attractive solution. The message reads "welcome to our firm Slovce".

INDUSTRY

General Industry

LOCATION

Manufacturer, Slovakia

APPLICATION DATE

2008

PRODUCTS

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Floor tiles

PHOTOS

1. Ramp entrance
2. Templates being placed
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

