


BELZONA EXTENDS RUBBER PUMP LINER LIFE

ID: 1104



PROBLEM

The rubber liner had limited life (up to 5 years). New liner cost 40,000 EUR

APPLICATION SITUATION

Warman pump circulating Gypsum slurry

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3.

BELZONA FACTS

New liner costs 40,000 EUR. Belzona coating cost 3,000 EUR and after 3 years in service shows no significant wear.

INDUSTRY

Power

LOCATION

Power Station, Poland

APPLICATION DATE

2005

PRODUCTS

Belzona 2121 (D&A Hi-Coat Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. General view of the pump
2. First coat applied
3. Second coat
4. completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

