

BELZONA SCREED REBUILDS DETERIORATING FLOORS

ID: 1111



PROBLEM

Water trapped beneath the red floor coating was causing odor and health concerns.

APPLICATION SITUATION

The original red epoxy coating was delaminating.

APPLICATION METHOD

Application completed in accordance with Belzona Know-How System Leaflet FPA-1. Heat lamps were used to accelerate the cure to ensure area ready for use the following day.

BELZONA FACTS

Belzona Magma Screed provides hard wearing surface that was applied overnight so causing minimum disruption to the store.

INDUSTRY

Buildings & Structures

LOCATION

Supermarket, British Columbia, Canada

APPLICATION DATE

2007

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete / Epoxy coating

PHOTOS

1. General view of problem floor showing delamination areas
2. Preparation of floor in progress using a Vacu-Grinder
3. Application of Belzona 4131 Magma Screed in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

