

BELZONA SCREED RESTORES DETERIORATED FLOORS

ID: 1112



PROBLEM

Water trapped underneath the failed coating was causing odour and health concerns.

APPLICATION SITUATION

The red epoxy floor coating was delaminating.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Heat lamps were used to accelerate cure to ensure area ready for use following day.

BELZONA FACTS

Belzona Magma Screed provides hard wearing floor covering that was applied overnight so causing minimal disruption to the store.

INDUSTRY

Buildings & Structures

LOCATION

Supermarket, British Columbia, Canada

APPLICATION DATE

2007

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete & Epoxy floor coating

PHOTOS

1. The delaminated coating was removed with scrapers
2. The area was ground with a Vacu-Grinder
3. Application of Belzona Magma Screed in progress
4. Completed application with heat lamps in place.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

