

BELZONA PROTECTS CHEMICAL CONTAINMENT AREA

ID: 1135



PROBLEM

Heavy deterioration of the concrete due to leakage and contamination during maintenance operations. The integrity of the structure was compromised.

APPLICATION SITUATION

Chemical containment area

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Special attention given to shimming and protecting base of support steelwork.

BELZONA FACTS

Area brought up to standard to meet required regulations. Additional protection for supports. Repairs easily carried out if required. Durable: During the last inspection in 2009, the containment area was in perfect condition.

INDUSTRY

General Industry

LOCATION

Food Processing plant, France

APPLICATION DATE

June 2003

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete, Steel

PHOTOS

1. View before repairs
2. View of the tank supports
3. View after shimming
4. Application completed with Belzona 4311 applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

